Start with indicator powered on and in normal weighing mode

1	SETUP / DRAFT	Press & hold setup key	Indicator will display "tArGEt"
2	SETUP / DRAFT	Press the setup key 3 more times to display CAL	**CAL**
3	A/M lb/kg OK UNITS	Press the OK key once	**UNItS**
4	A/M lb/kg OK UNITS	Ensure unit is set to kg, press the orange WEIGH key to toggle; Press OK	"Kg"
5	A/M lb/kg OK UNITS	Press OK key then Select current weigh bar	Display reads: "SCALE"
6	UNDO WEIGH	Display will show: AG-4t. Use orange WEIGH key to toggle	"AG-2t"
7	A/M lb/kg OK UNITS	Press the OK key to go to zero calibration	**2ErO**
8	A/M lb/kg OK UNITS	Press OK to enter live weight reading and capture zero	Display will read: 20.7 kg (flashing live weight)
9	A/M lb/kg OK UNITS	Press OK key again to capture zero	Display will now read: 0.0 kg (flashing)
10	→0← ZERO	To save and exit press the ZERO key	**SAviNG**